Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: PARSHALL 63-16H

Field Name: PARSHALL Well File #: 27437

Date Incident: 7/29/2014 Time Incident: 14:28 Facility ID Number:

County: MOUNTRAIL Twp: 152 Rng: 90 Sec: 16 Qtr: NW NW

Location Description:

Submitted By: Keith Kallberg Received By:

Contact Person: Keith Kallberg

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units
5 Barrels 5 Barrels 5 barrels

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/26/2015 Clean Up Concluded: 8/1/2014

Risk Evaluation:

N/A

Areal Extent:

On location around the open top tank.

Potential Environmental Impacts:

N/A

Action Taken or Planned:

The valve was closed to the open top tank stopping the release. Hydrovac was called in to remove the free fluid. A cleanup crew will come in after the tank is removed to scrape & remove the affected material. Fresh material will be brought in to replace what has been removed.

Wastes Disposal Location: Clean Harbors disposal at Sawyer ND

Agencies Involved: TAT & MHA

Updates

Date: 7/31/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location, according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.